

## **LEGEND**

⊖<sub>NP-1</sub> EXISTING NESTED SOIL GAS MONITORING

**PROBES** 

NESTED SOIL GAS MONITORING PROBES NO LONGER MONITORED DUE TO EXPANDED MINING

## GEOSYNTEC CONSULTANTS

LANDFILL BOUNDARY AND PROPERTY PERIMETER GAS MONITORING PROBES AZUSA LAND RECLAMATION LANDFILL AZUSA, CALIFORNIA

FIGURE NO. PROJECT NO.

3-1 CE4125-B11

DATE:

15 FEBRUARY 2000

DWG: 4125F137.DWG 199904271433 LP